

CERCLA REMOVAL ACTION DAILY WORK ORDER

181532



SITE NAME: Cornell-Dubilier Electronics Site
ORDER NO.: 2083
SITE/SPILL NO.: GZ
EPA REGION: II
CONTRACTOR: Earth Tech Remediation Serv.
MONITORS: None

CONTRACT NO.: 68-S2-99-08
DATE(s): 8/25/04
SHIFT: 0700 - 1530 hrs.
OSC: T. Budroe
WORK ORDER: 3
RM: J. Galioto

ALL OVERTIME MUST BE FIRST AUTHORIZED BY THE OSC PRIOR TO WORKING. ALL HOURS WORKED OFF-SITE MUST BE FIRST AUTHORIZED BY THIS OR ANOTHER WORK ORDER PRIOR TO WORKING AND MUST BE ACCOMPANIED BY AN OFF-SITE HOURS REPORT PREPARED BY THE INDIVIDUAL CONDUCTING THE WORK AND SIGNED BY THE RM.

DESCRIPTION OF WORK TO BE PERFORMED

- 1) Provide a **draft** form 1900-55 to the OSC for approval.
- 2) Mobilize to the Site and provide for cutting-down and removing all tree debris off-site for the white oak tree on the south-southeast portion of the property (backyard) and the three swamp maples trees on the north-northwest portion of the property. The subsurface soil should not be disturbed during this activity as the subsurface soil is contaminated. Ensure that this activity is fully insured.
- 3) Complete a Daily Work Summary outlining daily accomplishments.

NUMBER OF PERSONNEL AUTHORIZED

1-RESPONSE MANAGER 0-CLEANUP TECHNICIAN(S) 0-FIELD CLERK
0-CHEMIST 0-EQUIPMENT OPERATOR 0-FOREMAN 0-T&D COORDINATOR

EQUIPMENT AND EXPENDABLE MATERIALS AUTHORIZED

| ITEM | QUANT. | ITEM | QUANT. |
|-------------------------|--------|------------------|--------|
| PICK UP TRUCK (1/4 TON) | 1 | PASSENGER CAR | 0 |
| GARDEN SPRAYERS | 0 | BROOMS | 0 |
| LAPTOP COMPUTER | 0 | COMPUTER PRINTER | 0 |
| COPIER | 0 | VACUUM LOADER | 0 |
| FRAC TANK | 0 | AIR COMPRESSOR | 0 |
| CHAIN SAW | 0 | SAWZALL | 0 |
| DOUBLE DIAPHRAGM PUMP | 0 | SHOP VACUUM | 0 |

I CERTIFY THAT THE ABOVE WORK IS ORDERED AND AUTHORIZED BY THE CONTRACTOR IN THE PERFORMANCE OF THE ABOVE CITED DELIVERY ORDER

SIGNATURE OF ON-SCENE COORDINATOR

SIGNATURE OF CONTRACTOR'S REPRESENTATIVE

I ACKNOWLEDGE RECEIPT OF THIS WORK ORDER.